


Assembly Instruction 4550

CAUTION: Because of the edges some parts before assembly may be sharp, please handle unassembled parts carefully.


Parts List	Qty
A 	1
B 	1
C 	1
D 	1
E 	1
F 	1
G 	1
H 	1
I 	8
J 	1




1




2




3



4



5



6

