
















Assembly Instruction 2610




A  X28	B  X28	C  X12	D  X4	E  X60	I  M6x35 X8	J  X1	k  M6x16 X15	L  X31
G  X5	M  X8	N  X4	O  X4	F  X4	H  M6x30 X8	 60min		
①  X1 ②  X1 ③  X2 ④  X2								
⑤  X2 ⑥  X4 ⑦  X1 ⑧  X1								
⑨  X2 ⑩  X1								



3




4




5




6




7



8



9



10

