



Assembly Instruction 2230-6




A X24	B X24	C X4	D X24	E M6x35 X8	F X1	G X16
H X23	I X4	K M6x16 X15	L X5	 60min		

① X1	② X1	③ X2	④ X1
⑤ X2	⑥ X2	⑦ X1	⑧ X2
⑨ X1			


1




2




3




4




5





6




7



8



9



10

