

















Assembly Instruction 2230




A  X24	B  X24	C  X4	D  X24	E  M6x35 X8	F  X1	G  X16
H  X23	I  X4	K  M6x16 X15	L  X5	 60min		

①  X1	②  X1	③  X2	④  X1
⑤  X2	⑥  X2	⑦  X1	⑧  X2
⑨  X1			


1




2




3




4




5





6




7



8



9



10

