

















Assembly Instruction 2610-6




A  X28	B  X28	C  X12	D  X4	E  X60	I  M6x35 X8	J  X1	k  M6x16 X15	L  X31
G  X5	M  X8	N  X4	O  X4	F  X4	H  M6x30 X8	 60min		

①  X1	②  X1	③  X2	④  X2
⑤  X2	⑥  X4	⑦  X1	⑧  X1
⑨  X2	⑩  X1		



3




4




5




6




7



8



9



10

