


Assembly Instruction 4555

CAUTION: Because of the edges some parts before assembly may be sharp, please handle unassembled parts carefully.




Parts List		Qty
A		1
B		1
C		1
D		1
E		1
F		1
G		1
H		1
I		8
J		1


1




2




3



4



5



6

