






ASSEMBLY INSTRUCTION 51200



15MIN



A=1PC



B=2PCS



M8*20

C=16PCS



M8*16

D=16PCS



M8*12

E=16PCS



M5

F=1PC