






Assembly Instruction 2205-1




Parts List

①




x4

②




x1

③




x1

④




x1

⑤




x1

⑥




x1

⑦




x1

⑧




x1

⑨




x1

⑩




x1

⑪




x2

⑫




x1

⑬




x1

⑭




x1

⑮














x2

⑯




x2


Hardware List

A  φ8x30mm x12	B  x12	C  x12	D  x1
E  x1	F  M6x12mm x22	G  M6x25mm x4	H  x12
I  φ7x40mm x14	J  x8	K  φ3x16mm x8	L  φ3.5x14mm x48
M  x1	N  x8	O  x6	


Step 1




Step 2





Step 3





Step 4







Step 5




Step 6




Step 9




Step 10





Step 11




Step 12





Step 13





Step 14




Step 15




Step 16



Step 17




H




x12

Step 18



G




M6x25mm x2

E






x1



Step 19



Step 20



Step 21



Step 22

