




Assembly Instruction 2215-1




45min




Parts List

①




x2

②




x4

③




x1

④




x1

⑤




x1

⑥




x1

⑦




x1

⑧




x1

⑨




x1

⑩




x1

⑪













x1

⑫




x2


Hardware List

A  φ8x30mm x11	B  x8	C  x8	D  x1
E  x1	F  M6x12mm x24	G  φ4x35mm x4	H  x4
I  φ7x40mm x16	J  x8	K  φ3x16mm x12	L  φ3.5x14mm x24
M  x2	N  x4	O  x4	P  x4


Step 1




Step 2




Step 3




Step 4



Step 5





Step 6





x4



Step 7





Step 8




Step 9



Step 10



Step 11



Step 12

