
















Assembly Instruction 2225-1













45min





Parts List

①  x4	②  x2	③  x1
④  x1	⑤  x1	⑥  x1
⑦  x1	⑧  x1	⑨  x1
⑩  x2	⑪  x2	⑫  x1




Hardware List

A  φ8x30mm x12	B  x12	C  x12	D  x1
E  x1	F  M6x12mm x24	G  x6	H  x4
I  φ7x40mm x4	J  x12	K  φ3x16mm x12	L  φ3.5x14 x24
M  x4	N  x4		



Step 1





Step 2




Step 3





Step 4




Step 5




Step 6




Step 7





Step 8





Step 11



Step 12



Step 13



Step 14

